

SCHEDULE "C" TO BYLAW 40/2011

SCHEDULE "C" TO BYLAW 1/82 (AS AMENDED)
GAS PERMIT FEES

GST EXEMPT

		2012
	Residential Occupancy Not Exceeding 500,000 B.T.U.	
1. (a)	Installation with not more than 3 outlets which requires a meter	100.90
(b)	Installation with not more than 2 outlets which add to or extends existing gas equipment and does not need a meter	79.60
(c)	Additional outlets	16.00
(d)	Maintenance or repair work requiring a permit	79.60
(e)	Minimum Permit Fee	79.60
(f)	Interim Permit Fee or temporary installations	100.90
(g)	Inspection for restoration of gas service or to determine fitness of existing installations	79.60
(h)	Furnace replacement, gas fireplace installation, garage heaters, barbecues (Combination gas & heating permit)	79.60
	Commercial Occupancy and Residential Occupancy Exceeding	
2. (a)	For total input of 19.0 kW (65,000 B.T.U./h) or less	100.90
(b)	19.1 kW to 29.03 kW (65,001 B.T.U./h to 100,000 B.T.U./h)	106.00
(c)	29.3 kW to 117.2 kW (100,001 B.T.U./h to 400,000 B.T.U./h)	212.20
(d)	117.2 kW to 293.0 kW (400,001 B.T.U./h to 1,000,000 B.T.U./h)	254.40
(e)	293.0 kW to 1465.0 kW (1,000,001 B.T.U./h to 5,000,000 B.T.U./h)	297.20
(f)	1465.0 kW to 2930.0 kW (5,000,001 B.T.U./h to 10,000,000 B.T.U./h)	360.50
(g)	2930.0 kW or greater (10,000,001 B.T.U./h)	435.20
(h)	Laboratory burners	
	- first four (4) outlets or less	100.90
	- each additional outlet	5.40
(i)	Maintenance or repair work requiring a permit	100.90
(j)	Minimum Permit Fee	100.90
(k)	Interim Permit Fee or temporary installations	100.90
(l)	Inspection for restoration of gas service or to determine fitness of existing installations	79.60
	Propane Tanks	
3. (a)	Tank set with vaporizer and service lines	100.90
(b)	Tank set with no vaporizer	100.90
	General	
4.	Alberta Safety Codes Council Fee (collected on behalf of the Alberta Safety Codes Council)	Set by SCC
5.	In the event any work is commenced prior to the issuance of an applicable permit, the fees shall be doubled.	Double Fee
6.	Additional inspections required as a result of work being incomplete, building locked or inaccessible for inspection, or failing to meet the required standard will be charged a fee per inspection required.	100.00